


ねじ規格

Screw standard

ガス充填口 (POL) の寸法

Dimensions of gas charging port (POL)



備考


- 充てん口のねじは、JIS B 8245の付属書による。
- 充てん口70°面の角度の許容差は±3°とし、仕上げは、滑らかなこと。

Remarks

- For the screw of the charging port, refer to the Annex of JIS B 8245.
- The angle of the 70° face of the charging port has a tolerance of ±3° and is finished smoothly.

バルブの容器取付部の寸法

Dimensions of valve casing mounting section



(単位 Unit mm)

容器取付部記号 Casing mounting section symbol	ねじ部 Thread portion							m1 (約 Approx.)	m2 (約 Approx.)
	d ₄ (約 Approx.)	d ₅	基準径 d ₃	l ₁ (約 Approx.)	l ₂	ねじ山数 Number of threads (25.4 mmにつき)	テーパ Taper		
V ₁	21.2	18.661	20.000	11.6	22	14	3/26	3	2
V ₂	29.5	26.500	28.000	13.0	26	14	3/26	3	2

注記

- 容器取付部のねじは、JIS B 8245の付属書による。
- ねじ山の形状は、角度55°のねじ山に丸みをもつ三角ねじ(H1=0.6397P, r=0.1374P)で、軸心に直角なものとし、ピッチは軸心に沿って測る。
- ねじは右ねじとする。
- ねじゲージを手締めの状態ではめ合わせた時、ねじ部の末端は使用するねじゲージの末端から2山(ねじゲージの切欠きの範囲)以内とする。

Remarks

- For the casing mounting section, refer to the Annex of JIS B 8245.
- The screw thread is a triangular thread (0.6397P, 0.1374P) being rounded on the 55° screw thread, and perpendicular to the shaft center. The pitch is measured along the shaft center.
- The screw is a right-hand screw.
- When a screw gauge is fitted in the hand-tightened status, the end of the thread portion should be within 2 threads (notch range of the screw gauge) from the end of the gauge to be used.